

Division of Environmental Health  
140 Dameron Ave., Knoxville, TN 37917  
Phone: 865-215-5200 Fax: 865-215-5221 TDD: 865-215-2001

Knox County  
**Health Department**  
Every Person. A Healthy Person

Field #311	County # 47	Complete <input type="checkbox"/>
Facility: Fort Kid License #: N/A Address: 1050 Worlds Fair Park Dr.	Staff ID: 615 VN  Complaint Taken By: Kevin Clark Date Received: 10/22/2018 Time Received: 1:30 PM	Category: <input checked="" type="checkbox"/> unpermitted        Risk Category: Select...
Complaint Description:  Complainant concerned about safety of equipment/structures, and environmental hazards, present at playground.		

IF FOOD ILLNESS, PLEASE COMPLETE THE FOLLOWING QUESTIONS:

Date of Onset:	Medical Treatment: <input type="checkbox"/>	Duration:	Symptoms:
		Number of People:	
Medical Treatment Date:		Number of People ILL:	
Medical Treatment Facility:			

FOOD HISTORY: LIST THE FOOD EATEN WITHIN 3 DAYS PRIOR TO ONSET OF SYMPTOMS

Date:		Date:		Date:	
Breakfast:		Breakfast:		Breakfast:	
Lunch:		Lunch:		Lunch:	
Dinner:		Dinner:		Dinner:	

Disposition:

*See attached report.*

Person in Charge: <i>N/A</i>	Environmentalist: <i>Veretta Nadame</i>	Date & Time: <i>10/23/18 2:30-4:10pm.</i>
---------------------------------	--	--

DEPARTMENT OF HEALTH  
DIVISION OF GENERAL ENVIRONMENTAL HEALTH  
SUPPLEMENTAL REMARKS AND RABIES PROGRAM

ESTABLISHMENT OR NAME Fort Kid  
ADDRESS 1050 World's Fair Park Dr, Knoxville, TN DATE 10/23/18  
FO# 311 CO# 47 EST# N/A STAFF# 615 PROG -  
REFERRED TO \_\_\_\_\_ PROGRAM CODE -

- Blue Triangle Area -

- 1) Loose wood plants on jungle-jim playground equipment.
- 2) Exposed large, rusty nail inside wooden pole; top area of pole open.
- 3) Rubber bridge damaged / tripping hazard present and hole present in bridge. (Cat walk)
- 4) Splintered wood plank at bottom of signpost for Guidelines of Fort Kid.
- 5) Splintered wood plank leading to the Green Triangle Area.

- Spider Web -

- 1) Damaged rubber covering over chain.
- \* Note: Pea gravel on ground surface for playground.

Food Temperature Readings: \_\_\_\_\_

Sanitization Rinse Concentration/Temperature: \_\_\_\_\_

ENVIRONMENTALIST Veretta Nadashe TIME 2:30 - 4:10 pm  
OPERATOR \_\_\_\_\_ # VISITS \_\_\_\_\_

DEPARTMENT OF HEALTH  
DIVISION OF GENERAL ENVIRONMENTAL HEALTH  
SUPPLEMENTAL REMARKS AND RABIES PROGRAM

ESTABLISHMENT OR NAME Fort Kid  
ADDRESS 1050 World's Fair Park Dr., Knoxville, TN DATE 10/23/18  
FO# 311 CO# 47 EST# N/A STAFF# 615 PROG —  
REFERRED TO \_\_\_\_\_ PROGRAM CODE —

- Space Tunnel -

- 1) Splintered wood at entrance/exit of tunnel.
- 2) Exposed, raised nail heads.

- Fire Net -

- 1) Rubber tire(s) damaged.

- Circular Slide -

- 1) Splintered bench seat with loose nail located on the outside of bench.

- Haunted Maze -

- 1) Splintered wood plank near sign.
- 2) Wooden bench not in good repair/exposed nail.

Food Temperature Readings: \_\_\_\_\_

Sanitization Rinse Concentration/Temperature: \_\_\_\_\_

ENVIRONMENTALIST Veretta Hawane TIME 2:30-4:10pm  
OPERATOR \_\_\_\_\_ # VISITS \_\_\_\_\_



DEPARTMENT OF HEALTH  
DIVISION OF GENERAL ENVIRONMENTAL HEALTH  
SUPPLEMENTAL REMARKS AND RABIES PROGRAM

ESTABLISHMENT OR NAME Fort Kid  
ADDRESS 1050 World's Fair Park Dr., Knoxville, TN DATE 10/23/18  
FO# 311 CO# 47 EST# N/A STAFF# 615 PROG -  
REFERRED TO \_\_\_\_\_ PROGRAM CODE -

- Cat Walk -

- 1) Caution tape present to block off area which leads to the circular side area.
- 2) Exposed nail in plank at reconstructed bridge walk; splintered wood above wooden plank.

- Tree Fort -

- 1) Tripping Hazard present; exposed bolt in wood surface (plexi glass).
- 2) Missing bolts in wood around the plexi glass area surface.

- Double Slide -

- 1) Planks not in good repair at the entrance area and wood splintered.

Food Temperature Readings: \_\_\_\_\_

Sanitization Rinse Concentration/Temperature: \_\_\_\_\_

ENVIRONMENTALIST Veretta Nwame TIME 2:30 - 4:10 pm  
OPERATOR \_\_\_\_\_ # VISITS \_\_\_\_\_

DEPARTMENT OF HEALTH  
DIVISION OF GENERAL ENVIRONMENTAL HEALTH  
SUPPLEMENTAL REMARKS AND RABIES PROGRAM

ESTABLISHMENT OR NAME Fort Reid  
ADDRESS 1050 World's Fair Park Dr., Knoxville, TN DATE 10/23/18  
FO# 311 CO# 47 EST# N/A STAFF# 615 PROG -  
REFERRED TO \_\_\_\_\_ PROGRAM CODE -

- Jet Slide -

- 1) Loose, splintered wood surface at entrance.
- 2) Wood rails not in good repair.

Note: There is an area (section) of fence that is not complete.

Food Temperature Readings:

Sanitization Rinse Concentration/Temperature:

ENVIRONMENTALIST Veronica Navarre TIME 2:30 - 4:10 pm  
OPERATOR \_\_\_\_\_ # VISITS \_\_\_\_\_